. a Work Order ID 83280



Page 1

April-16-12 2:28:14 PM	1	O.).	700	- BAR	***	Page 1
Revision ID:U/R	48-141TRN oe Turning Detail	Accept	*N90004010	N *	Setup Start Stop	ו ביאו
Start Date: 16/04/2 Required Date: 30/04/2 Reference:	012 Start Qty: 1.00	*1* *1*	Cust Item ID: Customer:			*NS2*
	Date:		Date: Date:		Run Start Stop	"NR1"
Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID Tool # Plan Code		•	Reject Insp. Number Stamp
Draw Nbr D350-748-141	Revision Nbr					
*100 * Mori Seiki	MORI SEIKI CNC LATHE LARGE	0.00		, <u></u>	-	K 12-4-25
Mori Seiki CNC Lathe Large		mooth.	FA648			
*110 *110* QC Quality Control	QC1- Inspect dimensions to discover the dimension dimension dimensions to discover the dimension dimension dimension discover the dimension dimension dimension dimension discover the dimension dimension discover the discover discover dimension discover discov	0.00 0.00				Kc 12-4-25

Dart Aerospac	e Ltd	
---------------	-------	--

W/O:			V	VORK ORDER CHAN	GES					•
DATE	STEP	PRO	OCEDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Ca	tegory:	NCF	R: Yes	No DQ	A:	Date:	
	R	esolution:	Disposit	ion:	QA:	N/C Cld	sed:		Date:	
NCR:			WORK OR	DER NON-CONFORM	IANCE	(NCR)			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Secondary Action Description Chief Eng	ction B	Sign & Date	Verific Secti		Approval Chief Eng	Approval QC Inspector
								×		
										
		(i)	/ /-	311	_4					
			; 		4			- <u>-</u>	. 2.0	

0.00

Memo

140

Quality Control

QC

12-4-30

W/O:			W	ORK ORDER CHANG	ES				1	· · ·
DATE STEP		PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									Ģ.	
				+						
Part No	•	PAR #:	Fault Cat	egory:	_ NCF	R: Yes	No DQ	A:	Date:	
	Re	esolution:	Dispositi	on:	QA:	N/C CI	sed:		Date:	
NCR:			WORK ORE	DER NON-CONFORM	ANCE	(NCR)	•		
DATE	STEP	Description of NC			tion B	0:	Verific	ation	Approval	Approval
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector
									*	
						`				
									·	
							-			

Page 3

Insp.

170 Receive & Inspect for Damage & Mat'l Certs *170*

0.00

Packaging

0.00 Memo

Ensure Certificate of Conformity is attached

Heat Treat to min 180 KSI As per Dwg D350-748-141

(MIL-T-6736 OR AMS 2759-1C) Sand Blast tube after Heat Treat Possibe Supplier: Vac Aero

Packaging Ensure certificate of conformaty is attached

W/O:			W	ORK ORDER CHANGE	S				,
DATE STEP PROCEDURE CHANGE By Date	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
		•							
							Ē		
				2					
					1		<u> </u>		
Part No		PAR #:							
	R				QA: N/C Closed:				
NCR:		1	WORK ORD	ER NON-CONFORMA	NCE (NC	R)			
DATE STEP		Description of NC		Corrective Action Section		Verifi	cation	Approval	Approval
	JILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat		ion C	Chief Eng	QC Inspector
									÷
							÷ .		
		Φ.	- 3.						÷
					- 3-1				- 10

Quality Control

April-16-12 2:	28:14 PM		(). 12 ()()		
Item ID: Revision ID: Item Name:	D350-748-141TRN U/R Crosstube Turning Detail	Accept	*N9000	140100* Setup Star	14721
Start Date: Required Date	16/04/2012 Start Qty: 1.00	*1* *1*	Cust Item ID: Customer:	·	' *NS2*
Reference: Approvals:	Process Plan: QC:	Date: Toolin Date: SPC (-	Ston	"INK I"
Sequence ID/ Work Center I 180 *1 A \ * QC Quality Control	Operation Description QC6- Inspect dimensions t		Up/ Tool ID To Hours	Fool# Plan Accept Reject Code Qty Qty	Reject Insp. Number Stamp
*190 *100* Packaging Packaging	Packaging Memo Identify and st Location:	0.00 0.00 ck in kanban rack		Tw. 12	2-09-28
200 * 2 00* QC	QC21- Final Inspection - W	ork Order Release 0.00		12/	10/5/4
	Memo	0.00			\sim

CZ12109/28

Dail Ac	ospace Liu	i i			. 7			***
W/O:			WORK ORDER (CHANGES	1.44.0		,	. \
DATE	STÉP		OCEDURE CHANGE	В	y Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					Ī			
		×.	÷					¥
								1
							•	
Part No		PAR #:	Fault Category:	NCR: \	es No DC	A:	Date:	
	Resolution:	<u> </u>	Disposition:	QA: N/	C Closed: _		Date: _	
			WORK ORRED MON COM	=000000E (0	100)		· · · · · · · · · · · · · · · · · · ·	

NCR:	9	W	ORK OR	DER NON-CONFORMANCE	(NCR)			
		Description of NC		Corrective Action Section B	Verification	Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
					Color to the state of the state			
		÷ .			3			
				4.	Ä			, ,,,
- 			,	avalue.				
			,	•	**			
						•		
						C.		
						- 5		1

	83280
1,	
Part Number:	D350-748-141
	Page 1 of 1
	Part Number:

FIRST ARTICLE INSPECTION CHECKLIST

Inspection Sheet Drawing Dimension		Inspection Sheet Drawing Dimension Tolerance Dimen		Accept	Reject	Method of Inspection	Comments
	2.240	+0.005/-0.000	2.244	1			
	2.180	+0.005/-0.000	2.185		,		
	2.180	+0.005/-0.000	2.186.				
	2.237	+0.005/-0.000	2,242.	/			
	2.272	+0.005/-0.000	2.272				4
4	2.306	+0.005/-0.000	2.31/				
m	2.339	+0.007/-0.000	2.344				
SIDE	2.339	+0.007/-0.000	2.345				
•		, 4/1					
	0.062	+/-0.010	-062				
	4.26	+/-0.030	4.26				
Ĺ	R0.063	+/-0.010	063				
Į	R0.50	+/-0.030	.50				
	2.240	+0.005/-0.000	2.240				
	2.180	+0.005/-0.000	2.184				
	2.180	+0.005/-0.000	2,185	//			
	2.237	+0.005/-0.000	2241	//			····
	2.272	+0.005/-0.000	2.276	//			
m	2.306	+0.005/-0.000	2.311				
	2.339	+0.007/-0.000	2.344				
SIDE	2.339	+0.007/-0.000	2.24\$				
				1/			
	0.062	+/-0.010	.062		_		
	4.26	+/-0.030	4.26	4.26			
	R0.063	+/-0.010	163	//			
	R0.50	+/-0.030	.50				
	2			1			
	110.27	+/-0.060	110.27	1			

Measured by:	Audited by:	Preliminary Approval:	
Date: 12 - 4 - 24	Date: 13 -4-30	Date:	


Revised by	
K.I/.II M	Approved
	
	
	
_	KJ/EC/DD KJ KJ

Dart Aerospace L	.td
------------------	-----

	oop									
W/O:			V	VORK ORDER CHANGE	S					
DATE	STEP	PRO	OCEDURE CH	IANGE	Date	Date Qty Approval Chief Eng / Prod Mgr				
Ŧ										
Part No	•	PAR #:	Fault Ca	tegory:	NCR: Yes	No DQA	٨:	_ Date: _	ţ	
			Disposit	ion:	QA: N/C CI	osed: Date:				
NCR:			WORK OR	DER NON-CONFORMAI	NCE (NCR	1)		· · · · · · · · · · · · · · · · · · ·		
DATE	CTED	Description of NC		Corrective Action Section		Verific	ification Approval		Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector	
							*		:	
•						P				
**									52	
							4			
-							4			
					*					
			100							

DART AEROSPACE LTD	Work Order:	
Description: Crosstube Assembly (AS350/355 High Fwd)	Part Number:	D350-748-141
Inspection Dwg: D350-748-141 Rev: F		Page 2 of 2

WALL THICKNESS MEASUREMENT



	WALL	THICKNESS	MEASUREME	NT (IN)	Deviation	
Location	w1	w2	w3	w4	Δw (max-min)	TOLERANCE
READING 1 L= 0"	.127	. /22	. 121	. 127	006	
READING 2 L=	,147	.138	.130	134	.017	
READING 3 L=	.178	. 184	.176	.171	.013	
READING 4 L=	.180	. 181	.169	.171	.012	0.030"
READING 5 L=	. 181	.182	.173	.173	009	,
READING 6 L=	.138	. 136.	.137.	.139	.021	
READING 7	.125	.128	.126	126.	.001	

Calibration Result

Actual Block Thickness: 150-300

Sitescan 250 Measured Thickness: 100-300

Measured by:

Date: 12 - 9 - 27

Audited by:

Date: 12 - 4 - 30

Preliminary Approval:

Date:

Rev	Date	Change		Revised by	Approved
Α	06.11.09	New Issue (P/O D350-748-101)		KJ/JLM	7.55.0.00
В	07.10.24	Dwg Rev updated		KJ/EC/DD	
С	11.01.20	Dwg Rev updated		KJ	
D	11.07.26	Tolerance revised for 2.339 dimensions	•	KJ .O	1 ,1
E	12.06.04	Wall thickness form added		KJ dr	

D350-748-141 CROSSTUBE ASSEMBLY (AS 350/355 HI FWD) D6015-125 CROSSTUBE (OR D6017-115) 3 2 D3502-1 SUPPORT 4 D2856-400-710 ABRASION STRIP AELS-1032-225 INSERT

Description

WASHER (OR AN960JD10)

CLAMP (PER DART SPEC. M-MS21920-20)

Part Number

NAS1149D0363J

MS21920-20

MS27039-1-10

6 8

Item | Qty

-141

GENERAL NOTES:

1) MATERIAL: MANUFACTURED FROM D6015-125 OR D6017-115 FINISHED LENGTH = 110.270±0.06

MAGNETIC PARTICLE INSPECT PER DART OSI 038 4 2 CADMIUM PLATE PER AMS-QQ-P-416B, CLASS 1, TYPE II PRIME INSIDE AND OUTSIDE PER DART QSI 005 4.2 PAINT OUTSIDE PER DART QSI 005 4.2

TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.

UNITS: INCHES UNLESS OTHERWISE NOTED. BREAK SHARP EDGES: 0.005 TO 0.010 MAX.

IDENTIFICATION: DART PART NUMBER "D350-748-141" AND BATCH NUMBER ON INSIDE OF CUFF PER DART QSI 044 6.4 (VIBRATING STYLUS)

SCREW

WEIGHT: 30.45 lbs

Α

PART IS SYMMETRIC ABOUT CENTERLINE, EXCEPT FOR Ø0.297 HOLE.

BLEND OUT ALL EDGES FROM MACHINING LONGITUDINALY, TRANSITION SHOULD BE SMOOTH. NOTE: ALL HOLES ARE DRILLED AFTER BENDING.

10) BEND PROGRESSIVELY WITH A MINIMUM OF 7 PASSES. MAXIMUM TUBE FLATTENING DUE TO BENDING IS 6% BASED ON O.D.

11) HEAT TREAT TO MIN. 180 KSI. PER MIL-T-6736 OR AMS 2759-1C AFTER TURNING. ACCEPTABLE TO VERIFY TENSILE STRENGTH BY HARDNESS TEST PER ASTM E18 TO 40-45 HRC.

12) INSTALL D2856-400-710 ABRASION STRIPS WITH A GAP ON BOTTOM SIDE OF CROSSTUBE. CENTERED OPPOSITE D3502-1 SUPPORT, PER QSI 035.

13) EXTREME CARE MUST BE TAKEN TO PROTECT THE OUTSIDE SURFACE OF THE TUBE. THE OUTSIDE SURFACE MUST BE SMOOTH AND FREE FROM SURFACE DEFECTS SUCH AS SCRATCHES, NICKS, OR DENTS. DEFECTS UP TO 0.005" MAY BE BLENDED OUT LONGITUDINALLY. CIRCUMFERENTIAL GRIND MARKS ARE UNACCEPTABLE. WHEN DRILLING HOLES EXTREME CARE MUST BE TAKEN AND CAREFUL DEBURRING PERFORMED TO ENSURE A CLEAN HOLE WITH NO CRACKING/CHIPPING/GROOVES.

14) TORQUE CLAMPS 60 TO 80 IN-LB. ENSURE AT LEAST 1.5 THREADS SHOWING IN SAFETY AND THAT NUT HAS NOT BOTTOMED-OUT AFTER TORQUING.

15) MAX TWIST AFTER BENDING: WITH XTUBE LAYED FLAT ON SURFACE, THE DIFFERENCE BETWEEN CUFF HEIGHTS FROM THE SURFACE MAY BE NO LARGER THAN 0.25 (ZN C1-3).

SHOP COPY **RETURN TO ENGINEERING UNCONTROLLED COPY** SUBJECT TO AMENDMENT WITHOUT NOTICE

> WORK ORDER B3Z80 MLJ 12/04/16


> > **UNDER REVIEW**

В


ADD HRC TEST OPTION (B8-1) PER PAR 09-040, ADD TWIST LIMIT (A8-1, C1-3), ADD 06015-125 OPTION 10.11.23 (C8-1), STOCK DIM NOW MACHINED (D1-4) REVISE GENERAL NOTES; UPDATE TO CURRENT ADD STANDARDS; RELOCATED FLAG #6 PER PAR 08-046 09.09.30 (ZN A6-3); TOLERANCES (ZN C6-3, D1-3) D MAG. PARTICLE AND CAD PLATE AS MED. CP 06.10.31 С ADD CAD PLATING CP 06.08.14 В ADD D6017-115 & PRIME AND PAINT CP 06.06.30 Α NEW ISSUE CP 06.03.31 REV. DESCRIPTION BY DATE

DESIGN	91	□ DART AEROSPACE	I Th
DRAWN	97	HAWKESBURY, ONTARIO, CANA	
CHECKED		DRAWING NO.	REV. F
MFG. APPR.	E	D350-748-141 s	SHEET 1 OF 4
APPROVED	#	TITLE	SCALE
DE APPR.	#	CROSSTUBE (AS 350/355 HI FWD)) NTS
DATE 10.1	1.23	COPYRIGHT © 2006 BY DART AEROSPACE THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRES NOT TO BE USED FOR ANY PLANTAGE OR COMPOSED OR COMMUNICATED TO ANY WROTTEN FRAMESSION FROM DART ARROSPACE. TO	***********


	•									•
W/O:			W	ORK ORDER CHANG	GES					
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
										
										
Part No		PAR #:								
Resolution:			Disposition	n:	QA:	N/C Clo	sed:		Date:	
NCR:		\	WORK ORD	ER NON-CONFORM	ANCE	(NCR)				
DATE	STEP	Description of NC		ction B	<u> </u>	Verification		Approval	Approval	
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector



	-									
W/O:			W	ORK ORDER CHANG	ES					
DATE	STEP	PR	PROCEDURE CHANGE					Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
· · · · · · · · · · · · · · · · · · ·			•							·
				,						•
 										
Part No		PAR #:								
Resolution:			Disposition: QA: N/C Closed:						Date:	
NCR:			WORK ORD	ER NON-CONFORMA	MCE	(NCR)			
DATE	STEP	Description of NC	Corrective Action Se				Verification		Approval	Approval
DATE	SIEF	Section A	Initial Chief Eng	 Action Description Chief Eng 		Sign & Date	Secti	on C	Chief Eng	QC Inspector
					4					
					i i					1



	. Johno.	 							
W/O:			W	ORK ORDER CHANG	ES		-4		
DATE STEP		PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		÷	4				÷		
						ā			
		-						•	
		4.		Specific Acres 14					
Part No	:	PAR #:	_ Fault Cat	tegory:	_ NCR: Yes I	No DQA:		Date: _	
Resolution:			_ Dispositi	on:	_ QA: N/C Clo	sed:		Date: _	
NCR:		W	ORK ORI	DER NON-CONFORMA	ANCE (NCR)				
		Description of NC		Corrective Action Section		Verifica	tion	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector
		+		+			-		
						:			
				· · · · · · · · · · · · · · · · · · ·					
•									



Dart Ae	rospace	Ltd								4.3		
W/O:			W	ORK ORDER CH	IANGES				1.0.1			
DATE	STEP	STEP PROCEDURE CHANGE					Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
·		• 10			- A - A - A				62.0			
				,	•	ari C			oración (/ Kink		
Part No		PAR #:										
NCR:		We	ORK ORI	DER NON-CONFO	ORMANCE	E (NCF	R)		, <u></u>	~		
		Description of NC	Corrective Action Section B				Verification		Approval	Approval		
DATE	STEP	Section A	Initial Chief Eng	Action Descri Chief Eng		Sign 8	Sect	Section C				QC Inspector
							\$10°			÷		
:												



Certification '

SOLD TO

Dart Aerospace Ltd. 1270 Aberdeen Street Hawkesbury, ON K6A 1K7

June 5, 2012

Metlab Shop Order No:

72197

Purchase Order:

16899

Description:

Crosstube

Part No.:

D350-748-141TRN, D350-748-241TRN

Quantity:

7 and 4 Pieces, Respectively

Weight:

500 Pounds

Material:

4130 Alloy Steel

Specifications:

Heat Treat to Minimum 180 KSI (MIL-T-6736OR AMS 2759-IC)

Note:

Need HRC 40 - 45

This is to certify that the above parts were processed as indicated above and conform to the specification requirements.

Results:

HRC 45 (218 KSI Tensile Strength, Converted)

Quality Representative

Mark Podob

MERCURY CONTAMINATION: During the heat treating process, testing and inspections, the product did not come in direct contact with mercury or any of its compounds nor with any mercury containing device.



Heat Treating and Metallurgical Consulting